S.J.D	
HOMES	

Policy No:

Review Date: 24th October 2023

Date of Next Review:

23rd October 2024

PREMISES RESOURCES

Policy Statement

We aim to provide a homely, welcoming environment for our service users, but we are mindful that they are also workplaces. Workplace legislation is varied and complex and this policy has a wide-ranging content encompassing the general workplace environment including internal and external areas.

The Policy

It is important that regular assessments of the premises, both internal and external, are undertaken and that any repairs, or risks identified are dealt with in a timely manner. All assessments are recorded, monitored and audited as part of our Health and Safety Quality Assurance System

Asbestos

Asbestos is likely to be present if the building was constructed or refurbished between 1950 and 2000, particularly where it has a steel frame and or boilers with thermal insulation.

An asbestos survey is undertaken by the Landlord in order to identify exposure risks for employees and service users where there is no or limited information on the premises. The survey will show:

- Its location
- The type of material (lagging, tiles, partition) etc.
- Its condition
- The type of asbestos (blue, brown or white)

Radon

Radon is a naturally occurring radioactive gas that can seep out of the ground and build up in houses and indoor workplace located in a "radon-affected area". Information on the location of a radon affected area, and the degree of likely risk, can be found on the UK Radon website (www.ukradon.org)

The highest levels are usually found in underground spaces such as basements but high concentrations can also be found in ground floor buildings because they are usually slightly lower pressure than the surrounding atmosphere. This allows radon from subsoil to enter through cracks and gaps in the floor, if appropriate precautions are not taken.

Radon assessment should be carried out in any building or basement where its location and characteristics suggest that elevated levels may be found and significant exposures to employees and/or other people are possible. Assessment is needed for all workplaces below ground and all workplaces in radon-affected areas. Inexpensive surveys can be carried out by leaving small, plastic, passive detectors in appropriate locations.

Assessments Surveys and assessments are to be carried out.

Gas Safety

Gas appliances, and associated pipework, flues and ventilation, are checked for safety at least once a year by Gas Safe registered engineers. Servicing is carried out at the same time to ensure they are maintained in a safe condition. Registered engineers carry out any work on gas appliances and pipework. Liquefied petroleum gas (LPG) installations and service pipework are also inspected and maintained to ensure that they are in a safe condition. Assessments and servicing are carried out.

Fire Safety

Although serious fires in care homes are fairly rare, when they do occur they can be catastrophic. As an organisation we have responsibility for the premises and take precautions to prevent fire.

Our Fire Safety Risk Assessment is kept up to date, and we use it to ensure that necessary fire safety measures are in place. It identifies what could cause a fire, including:

- Sources of ignition (eg heat or sparks)
- Materials that burn
- People who may be at risk

Simple control measure include:

- Keeping sources of ignition and flammable substances apart
- Ensuring good housekeeping (eg avoid build-up of rubbish)
- Considering how to detect fires and how to warn people quickly if they start. Special arrangements may be required if service users have mobility issues
- Having the correct fire-fighting equipment and ensuring these are correctly maintained
- Keeping fire exits and escape routes clearly marked and unobstructed
- Ensuring staff receive appropriate training

Working at Heights

Before working at height all staff must assess the risk through the following steps.

- avoid working at height where it is reasonably practicable to do so
- minimise the distance and consequences of a fall, by using the right type of equipment where the risk cannot be eliminated
- do as much work as possible from the ground
- ensure that staff can get safely to and from where they work at height
- ensure equipment is suitable, stable, strong for the job, maintained and checked regularly
- ensure that staff don't overload or overreach when working at height
- take precautions when working on or near fragile surfaces
- provide protection from falling objects
- consider the emergency evacuation and rescue procedures
- if a ladder is the right piece of equipment for these activities it must be the right type, and that it is checked, in a safe condition, and used safely.
- Where safety fixtures and fittings are installed, ensure they are functioning effectively and have not deteriorated as a result of use, wear or tampering.

Contractors

Contractors can include window cleaners, gardeners and contract cleaners. SJD Homes and the contractor have responsibility for health and safety and together ensure that adequate risk assessments are in place to reduce the risk to employees, the contractor's employees and others in the home. When a contractor is working at height it is our responsibility to ensure they are doing the work safely and are not putting others at risk, eg taking safe access into account and providing protection from falling objects.

Outside areas and vehicle movements

It is important to ensure that the garden and outdoor areas, such as ponds, steps/paths, greenhouses, swimming pools or balconies, do not pose a significant risk to service users, visitors, staff and members of the general public. We carry out risk assessments and where possible manage risks so that outdoor environment and their participation in activities is not unduly restricted.

We consider 3 key areas during assessment:

- Are the outside areas safe? Has the safety of vehicle routes and speeds, parking, lighting, location and unloading of deliveries, visibility and signage, driving surfaces and segregating people and vehicles been assessed?
- Is the work vehicle safe? e.g. for transporting service users, are they safe for their intended use?
- Are people safe? Do visitor and contractors follow the arrangements we have in place, and are employees safe to transport service users?

Doors and Gates

Doors and gates in areas of the building where service users have access are designed so they can be opened easily and are not fitted with strong self-closers. In some instances, where is does not cause an obstruction, we have re-hung some doors to open outwards, eg in toilets and bathrooms, as this improves access for emergency access to areas where staff may need to assist a service user. Locks that can be over-ridden by staff in the event of emergencies are in place in these areas.

The security of doors and gates are assessed, especially where it has been identified that specific service users leaving the premises will present a significant risk to their safety. In some instance devices that alert staff of service user's location and whether they are at risk harm could be installed. Where doors or gates are accessed via a key code system, due regard must be given to the Mental Capacity Act 2005 and any DoLS situation which may arise in the use of such systems.

Ventilation and Heating

Premises need to be ventilated with clean, fresh air to provide the right environment for service users and staff. Ventilation or air conditioning systems are maintained to the manufacturer's schedule.

Training Statement

Staff with H&S responsibilities including maintenance personnel, have the appropriate up-to-date qualifications. Outside contractors and specialists used by SJD Homes are required to be registered with the appropriate body and produce evidence of their qualifications and registrations.

Related policies

Accident and Incident Reporting (RIDDOR) / COSHH Business Contingency and Emergency planning Environmental Management Good Governance Health and Safety Premises Access – staff and Volunteers Premises and Resources Risk Assessment